

Message

From: Levo, Brian [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=25404739F3BD46DC95B0DE1CFAD58BB4-LEVO, BRIAN M.]
Sent: 1/29/2019 9:36:22 PM
To: Vojik, Matthew [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=807fcc9fdcae4fa5951da79c66e9003f-Vojik, Matthew J.]
Subject: TASCO Twin Falls - Noncompliance
Attachments: 24h NonCompliance Report 012919.pdf

Matt, as discussed see the 24-hr noncompliance report attached. Something worth looking into during your inspection there.

Thanks,

Brian Levo
NPDES Enforcement Coordinator
Water and Wetlands Enforcement Unit
U.S. Environmental Protection Agency - Region 10
1200 6th Avenue, Suite 155, MS OCE-201, Seattle, WA 98101
Phone: (206) 553-1816, Fax: (206) 553-4743